

Standard Plans – Changes – April 1, 2014

The following plans will go into effect for the July 2014 Letting

Typical Cross Sections

3850-2-E-20 – Joint/Pavement Repair replaces 3850-2-E-19

3851-2-E-14 – Joint/Pavement Repair (Overlay) replaces 3851-2-E-14

Revisions listed below:

1. Labeled all sheets (ie. overlay only joint repair, no overlay plain concrete repair)
2. Labeled sketches of plain, reinforced and doweled concrete repairs
3. Filled in joint and crack sealing sketches
4. Added verbage to detail the sketches better
5. Added “tooled longitudinal joint” sketch/detail to all sheets with full depth and partial depth repairs
6. Removed 3’ x 3’ full depth wedge repair
7. Defined tie bar and dowel bar placement and removed “traffic flow” arrow

If you have questions call Deb Larson at 402-479- 4624