

Changes – May 16, 2013

**Standard Plan**

Control Joints for Concrete Box Culverts 4040-0-E-04

This plan was moved to the active folder by mistake. It should not have been moved.

So the current plan is **4040-0-E-03**

Here are a few new pages just so you can keep your book updated. **PLEASE pull out 4040-0-E-04 and put in 4040-0-E-03.**

If you have questions call Phil TenHulzen at 402-479-3951.