WILDLIFE UNDERCROSSINGS




SARPY DITCH BRIDGE
New Undercrossings
Existing Undercrossing
Old Deer Path Across I-80
Photo Brian Johnson, NDOR

Existing Sarpy Ditch UnderCrossing



PROBLEMS
--Limited Vertical Clearance (<8')
--Presence of a Ledge
--Broken Concrete
--Limited Field of View

Photo Brian Johnson, NDOR

Typical NDOR Channel Protection

Photo Brian Johnson, NDOR

Sarpy Ditch Wildlife UnderCrossing

Photo Brian Johnson, NDOR

Woven Wire Deer Fence



Electrobraid Wildlife Fence



Electrobraid’s Braided Electric Rope
(Actual Rope to be black)